



Thermography Report

Customer / Site

Address

Thermography Date

Thermographer

ModifiedDate

EXECUTIVE SUMMARY

An Infrared Thermal Inspection was performed at the site noted on the preceding Title Page.

PLANT INSPECTED

All of the facilities examined during this visit are listed on the following pages.

FOLLOW UP INSPECTION

We would recommend further Infrared Thermal Inspections at twelve (12) monthly intervals. This will assist you with the effective maintenance and reduction of unscheduled outages and failure of your facilities.

We thank you for the opportunity to carry out the Infrared Thermal Inspection and look forward to a continued mutually beneficial association.



This is to certify that


Michael Reiken

attended

Infrared Thermography for Condition Monitoring

Level 1 Certification Program

in Melbourne, 7 – 11 February 2005



Dr Alan Smith
Deputy Head
Department of Mechanical
and Manufacturing Engineering
University of Melbourne



Fault Diagnosis - Criteria

Rating	Δ Temp	Recommendations
low	0 to 10°C	Possible deficiency and warrants further monitoring.
moderate	10 to 20°C	Indicates deficiency; repair as time permits.
high	20 to 40°C	Corrective measures required ASAP.
extreme	40° and above	Corrective measures required immediately

REPORT GUIDELINES - GENERAL

This report has been prepared in accordance with the "Guideline for Infrared Inspections of Electrical and Mechanical Systems" First Edition, Copyright 1993 Infraspection Institute Inc.

The subsequent delta T (temperature difference) criteria applied to evaluate the temperature severity of an exception, is the "Experienced-based" criteria for electrical and/or mechanical equipment.


This report is designed to caution against temperature anomalies and/or exceptions that may indicate the possible deterioration or failure of a component or system. It is not a guarantee against failure, nor is it a quantitative measure of deterioration or malfunction. This report serves only as an indication of an exception which may or may not lead to deterioration or failure. It is the responsibility of the contracted end user to resolve the diagnosis and determine any corrective measures, if required. Excel Power is not responsible for determining fault diagnosis or rectification procedures, and as such, it is recommended that all faults be investigated by qualified personnel of the end user.

In no event shall Excel Power be liable to anyone for special, collateral, incidental or consequential damages in conjunction with or arising from the use of this survey


Inspection Summary



Image Date	Barcode	Location	Object ID	Page number	Fault Rating
	00001229	Main Switchboard	Changeover Switch	5	1 Normal
	00001229	Main Switchboard	Distribution Section	6	1 Normal
	00001229	Main Switchboard	DB1a	7	1 Normal
	00001233	Coldroom outside	Distribution Board	8	1 Normal



FLIR0336.jpg



File information

Created	17/01/2024 12:06:00 PM
Camera model	FLIR T540
Camera serial	79320250
Lens	FOL18D
Emissivity	0.98
Atmospheric temp.	24.0 °C

Measurements

Sp1	37.4 °C
Li1	
Max	38.3 °C
Avg	36.6 °C
Min	34.2 °C





Image Data


Company	
Barcode	00001229
Location	Main Switchboard
Object ID	Changeover Switch
Fault Description	No thermal fault found
Remedy	Maintain regular thermal imaging inspections
Fault Rating	Normal
Thermographer	

Corrective Action Performed:

Work Performed	Repaired By:
	Date:



FLIR0337.jpg




File information

Created	17/01/2024 12:09:23 PM
Camera model	FLIR T540
Camera serial	79320250
Lens	FOL18D
Emissivity	0.98
Atmospheric temp.	24.0 °C

Measurements

Sp1	36.8 °C
Li1	
Max	37.4 °C
Avg	36.4 °C
Min	34.9 °C

Profile



Fault Rating


1 Normal

Image Data


Company	
Barcode	00001229
Location	Main Switchboard
Object ID	Distribution Section
Fault Description	No thermal fault found
Remedy	Maintain regular thermal imaging inspections
Fault Rating	Normal
Thermographer	

Corrective Action Performed:

Work Performed	Repaired By:
	Date:



FLIR0338.jpg




File information

Created	17/01/2024 12:10:33 PM
Camera model	FLIR T540
Camera serial	79320250
Lens	FOL18D
Emissivity	0.98
Atmospheric temp.	24.0 °C

Measurements

Sp1	36.4 °C
Li1	
Max	37.0 °C
Avg	36.4 °C
Min	35.4 °C

Profile



Fault Rating



1 Normal

Image Data

Company	
Barcode	00001229
Location	Main Switchboard
Object ID	DB1a
Fault Description	No thermal fault found
Remedy	Maintain regular thermal imaging inspections
Fault Rating	Normal
Thermographer	

Corrective Action Performed:

Work Performed	Repaired By:
	Date:



FLIR0339.jpg

File information

Created	17/01/2024 12:28:13 PM
Camera model	FLIR T540
Camera serial	79320250
Lens	FOL18D
Emissivity	0.98
Atmospheric temp.	24.0 °C

Measurements

Sp1	44.8 °C
Li1	
Max	48.1 °C
Avg	42.6 °C
Min	39.3 °C




Image Data

Company	
Barcode	00001233
Location	Coldroom outside
Object ID	Distribution Board
Fault Description	No thermal fault found
Remedy	Maintain regular thermal imaging inspections
Fault Rating	Normal
Thermographer	

Corrective Action Performed:	
Work Performed	Repaired By:
	Date: